

OK

2005 Annual Report Review

Permittee:	Savage Services Corporation	
Mine Name:	Savage Coal Terminal	
Permit Number:	C/007/022	
Date Report Received:	March 31, 2006 @ Price DOGM	
Assigned Reviewers:	Peter Hess, Engineer / Inspector <i>PHH by av</i>	Date Completed September 27, 2006
	David Darby Hydrology <i>DD</i>	December 6, 2006
	Joe Helfrich, Biology <i>JH</i>	June 2, 2006

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

Assignments:

Inspectors: Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.
Hydrologists: Review Water Monitoring Data, Precipitation and Climatological Data, Non-Coal Waste
Biologists: Review Vegetation/Revegetation Success Monitoring, Raptor Survey
Engineers: Review Subsidence Monitoring Data, Annual Impoundment Certification, Annual Overburden, Spoils, Refuse, Floor, etc.

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Cover Sheet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Information provided in the cover sheets appears to be complete and adequate.
AVS; Legal/ Financial Update	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The Annual Report of Officers has been submitted to the Utah Department of Commerce and is on file at DOGM
Mine Sequence Map	<input type="checkbox"/>	<input checked="" type="checkbox"/>	No site maps have been provided to the DOGM as part of this annual report for 2005. The Permittee added additional surface facilities during 2006. Prior to the date of this review, (9/27/2006) the Permittee was required to update surface facility and surface drainage maps. Same have been P.E. certified and incorporated into the mining and reclamation plan.
Water Monitoring Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No summary report was required or submitted. All required data was submitted electronically in a timely manner. See quarterly water-monitoring reports for detailed review.
Precipitation & Climatological Data	<input type="checkbox"/>	<input checked="" type="checkbox"/>	No summary report was submitted. Values for average annual precipitation, wind direction and high and low temperatures are in the MRP.
Non-Coal Waste report	<input type="checkbox"/>	<input checked="" type="checkbox"/>	The MRP requires that all non-coal waste be disposed of within a State permitted landfill. All non-coal waste is temporarily stored in metal containers prior to off-site shipment.

2005 Annual Report Review

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Subsidence Monitoring Data	<input type="checkbox"/>	<input checked="" type="checkbox"/>	This site does not extract coal from an underground deposit. This is a storage/blending/shipping facility.
Annual Impoundment Certification	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Appendix A of the annual report contains fourth quarter and annual impoundment inspections / P.E. certifications for sediment ponds 1,2,3, 5 and 6. None of the five impoundments had signs of instability, structural weakness, or other hazards reported. All ponds were reported as having 0.1 to 0.5 acre feet of sediment storage capacity remaining. All ponds were cleaned during the summer of 2006. Mr. Dan Guy, Utah registered professional engineer certified all 4 th quarter / annual inspection reports as required under R645-301-514.310-311.
Annual Overburden, Spoil, Refuse, Floor, etc.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Appendix A also contains the four quarterly P.E. inspections / certifications conducted of the refuse pile facility for 2005. Some material was removed from the North end for shipment to Sunnyside Co-generation Associates per approved DOGM permitting action. Coal was also temporarily stored on the East end of the pile where refuse had been removed. No safety hazards were noted during any of the quarterly inspections. All reports have been certified by Mr. Dan Guy, Utah registered professional engineer. The submittal of laboratory analyses of refuse material is not required at this time.
Vegetation Data	<input type="checkbox"/>	X	Not required
Revegetation Success Monitoring	<input type="checkbox"/>	X	Not required
Raptor Survey	<input type="checkbox"/>	X	Not required
Other Information	<input type="checkbox"/>	<input type="checkbox"/>	

O:\ANNUAL_RPT\2005 Annual Reports Reviews\Savage AR_05.doc